



Correct Line of Street
36

37

Museum

Erroneous Street

Queen's Bastion

King's Curtain

Built since 1992

Construction Roads

Marsh

Place d'Armes (not excavated)

Toe of Glacis

Remnant Doors for Casemates 6 & 7 Left
6 7

Glacis

Left Flank
1 2 3 4

Left Face Escarp
Main Ditch
Counterscarp

Star Fort Ditch

Snow Fence to Protect Work Area from Visitors

British Graves Area

Portable Plastic Shelters

Section of Cobbles in Central Passage of Chateau

Flanked Angle

Entrance to Countermine Tunnel

Townward Defences
Epaulement

Brick Doorway (Only Portions of Original Left after Reconstruction)

Excavation for Interior Revetment Reconstruction

Covered Way

Revetment of the Covered Way

16

17

Postern Tunnel
Inner End
Outer End

Right Flank Casemates
6 7

Right Re-entrant

Visitors Shelter

Work Shed

Dauphin Curtain Test Excavation

Revetted Glacis

Place d'Armes